Canon

SERVICE BULLETIN COPIER

Issued by Canon Europa N.V.

Model: **Multi PDL Board-B1**
Printer Board-P3

No.: GP-GEN-004
(97QAB-0040)
DATE: 19.12.97

LOCATION: **Multi PDL Board-B1 / Printer Board-P3**
SUBJECT: **Firmware Version Up (ver. 4.01)**

1. Outline

Multi PDL Board-B1 and Printer Board-P3 ver.4.01 were released.

2. Details

As Multi PDL Board-B1 and Printer Board-P3 ver.4.01 were released., the modification from ver.3.04 fixes the following problem:

When “Multi Size/Orientation Job” is selected by the GP PCL Printer Driver and printing is executed with “GP Envelope Feeder Attachment” installed, printing on an envelope turns upside down.

3. Combinations of ROMs

GP200/215	IP	Ver.42.05 and later
	D-Con	Ver.35.04 and later
	PRCON	Ver.7.01
	PS/PCL	Ver.4.01
	PCL5e	Ver.4.01
	NIB-E3	Ver.30.06
	NIB-E3e	Ver.2.24

4. Remarks

When printing is executed on an envelope using Post Script Printer Driver, it is necessary to execute print after “Rotated Landscape” is selected with User Interface of the PS Driver.