Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : Multi-Output Tray-D1

No.: Acc-135
(FF-T01-W-000034-01)

DATE: 08.01.99

Location : MULTI-OUTPUT TRAY

Subject : DIFFERENCES BETWEEN MULTI TRAY-D1 (FOR GP400 SERIES) AND MULTI TRAY-C1 (FOR GP215 SERIES)

Reason : The Multi Tray-D1 is based on the Multi Tray-C1, with the differences discussed herein.

Details :

1. Major Differences
   - To accommodate the increase in the speed of the host copier, the feeder motor, inlet switching flapper solenoid, and 2/3-bin switching flapper solenoid have been modified to increase delivery/feeding speed.

2. Serial Numbers
   F24-8311-700 : ZSG00001 and later

3. Points to Note for Servicing Work

①Service Manual
See the Service Manual for the Multi Tray-C1 (FY8-13EB-000). (For the periodically replaced parts and consumables/durables, see also the Multi Tray-C1 Service Manual.)

②Parts Catalog
See the parts Catalog for the Multi Tray-C1/D1 (FY8-31CL-020).

4. Difference in Service Parts

FIGURE & KEY No.	C1 (GP215 series) Part number	D1 (GP400 series) Part number	Q'ty	Description	Remarks
Q30-47	FE9-0083-000		1	HOLDER, BIN, FRONT	
Q10-11		FB4-3789-000	1	SPACER, TRAY	
Q10-14		FB4-3796-000	1	DAMPER, TRAY	
Q30-6	FB3-3780-000	FB4-3780-000	1	GUIDE	
Q30-8	FB3-3782-000	FB4-3781-000	2	LINK, SOKENOID	
Q30-17	FB3-3804-000	FB4-3785-000	1	GRIP, GUIDE	
Q30-18	FF5-4839-000	FF5-7209-000	1	DEFLECTOR, 1	
Q30-18A	FB3-3787-000	FB4-3783-000	1	SHEET, DEFLECTOR	
Q30-20	FF5-4840-000	FF5-7214-000	1	MOUNT, MAGNET, FRONT	
Q30-22	FF5-4846-000	FF5-7211-000	1	PLATE, UPPER	
Q30-23	FF5-4847-000	FF5-7215-000	1	MOUNT, MAGNET, REAR	
Q30-14	FF5-5643-000	FF5-7210-000	11	PLATE	
Q30-24	FH6-1273-000	FH6-1478-000	1	MOTOR, STEPPING	
Q30-25	FH7-5665-000	FH7-5831-000	2	SOLENOID	
Q30-28	FS5-2317-000	FS6-2824-000	2	SPRING, TENSION	
Q30-35	FS6-2388-000		1	SPRING, COMPRESSION	
Q30-37	RB1-3130-000		1	PIECE, DRG, PRESSURE	
Q30-19	XF9-0570-000	XF9-0660-000	1	BELT, TIMING, 218T	