Canon SERVICE BULLETIN COPIER
Issued by Canon Europa N.V.

MODEL: NETWORK PRINTER BOARD-F1

No.: GP-GEN-024
(99-OIPD0-B0027)
Date: 07.05.99

LOCATION: SYSTEM SOFTWARE/USER SOFTWARE

SUBJECT: SYSTEM SOFTWARE V1.01A/USER SOFTWARE V1.01A/V1.01B

System Software V1.01A and User Software V1.01A/V1.01B of Network Printer Board-F1 (GP-F1) were released.

REASON

Upgrade

History of System Versions

Service Bulletin	Ver. No.	Description
	System Soft. V1.01A User Soft. V1.01A/1.01B	Defects modified.
GP-GEN-017	Ver. 1.01	Added specifications and modified defects - Image Runner Support - The defect caused when multiple GP F1 exist on the same network by Auto Configuration was modified. - Boot ROM upgrade
	Ver. 1.00	New Release

DETAILS

1. Here are the modifications in Network Printer Board-F1 System Software V1.01A as compared with V1.01.

No.	Item	Description
1.1	Accented characters appeared as Kanji characters on the LCD panel	The defect that accented French and German characters used in text names are displayed in Kanji characters on copier LCD was modified.
1.2	Very long Server names together with long Apple Talk queue names in some languages caused only the Hold queue being visible	The defect that only Hold Queue appears in the Print Queue of Apple Talk if a server name of GP PS-F1 is long (e.g. 21 characters) in some languages (e.g. French) was modified.
1.3	System Version Number	The version number was changed from V1.01 to V1.01A (LCD panel, Configuration Print and so forth).

2. Here are the modifications in Network Printer Board-F1 User Software V1.01A as compared with V.1.01.

No.	Item	Description
2.1	Some DLL files do not support European languages internally	=NT4.0 PS Driver= cngp60ui.dll, cngp60um.dll – These are the files that the language string were in English only in V1.01, and needed to be localized, and it was recompiled into the proper languages.
2.2	Auto Configuration does not work under certain environments due to an error in creating the driver	=Windows95/98 PS Driver= Auto Configuration does not work when an address with 3 digits is entered in the second octet in Auto Configuration using the IP address. However, printing operates without a problem. [Workaround] - Use the Printer Driver V1.01B - Use Manual Configuration
2.3	Version Number	The version number for the printer driver continues to be V1.01.
2.4	Others	No modifications in Macintosh Printer Driver and Fiery Utility.

3. Here are the modifications in Network Printer Board-F1 User Software V1.01B as compared with V1.01A.

No.	Item	Description
3.1	The defect of Auto Configuration which does not work in V1.01A was modified	=Windows95/98 PS Driver= Please note that in case 240 or more is specified in the first octet of the IP address, Auto Configuration does not operate normally due to restrictions existing in common with NetSpot dll. Since the network with 240 or more specified for the first octet of the IP address is called “Class E” and is used only in experimental environments of Internet, no actual damage will be done in the user environment.
3.2	Version Number	The version number of the printer driver continues to be V1.01.
3.3		No modifications in the NT4.0 PS Driver, Macintosh Printer Driver and Fiery Utility.

COMBINATION OF ROMs

GP605/605P	IP	Ver. 4.06 or later
GP605/605P	MFC	Ver. 6.02 or later
GP F1 Boot ROM		Boot Block: 1.4.49 Main Block: 1.4.49c
GP F1 System		Ver. 1.01A

REMARKS

When you use the V1.01A/V1.01B printer driver, do not fail to remove the old version.

AFFECTED MACHINES

Under investigation

SERVICE PARTS

No modifications