Code	Contents	Remarks	
		Causes	Check procedures/corrective measures
C083	**Flash ROM program area checksum error** • A checksum error occurred with the program in the flash ROM on the fax control PCB.	Defective SRAM on the fax control PCB.	Replace the fax control PCB and check for correct operation.

1-5-1 Self-diagnosis

(1) Self diagnostic codes

Code	Contents	Remarks	
		Causes	Check procedures/corrective measures
C003	**Fax control PCB system problem** • Processing with the fax software was disabled due to a hardware or software problem.	Defective fax control PCB.	Replace the fax control PCB and check for correct operation.
C005	**Communication problem between the operation unit PCB and fax control PCB** • The operation unit PCB did not receive any key request command from the fax control PCB within 1 minute of the status change signal turning on. Then, after resetting the fax machine, the operation unit PCB again did not receive any key request command from the fax control PCB while the status change signal was held on for 1 minute. • Abnormal data was received 5 times in succession in response to the command from the fax control PCB. • An erroneous FAX READY signal continued for 3 seconds and, after resetting the fax machine, an erroneous FAX READY signal continued for 3 seconds again.	Defective fax control PCB.	Replace the fax control PCB and check for correct operation.
C006	**Communication problem between the main PCB and fax control PCB** When the facsimile is in the condition given below, the correct status was not received after 5 transmission retries. • When a communication error, such as a parity error, occurs while receiving status. • When no status is sent back within 100 ms of sending a command. • When the interval of status reception data exceeds 30 ms.	Defective fax control PCB.	Replace the fax control PCB and check for correct operation.
C013	**Fax control PCB software switch checksum error** • A checksum error occurred with the software switch value stored in the flash ROM on the fax control PCB.	Defective SRAM on the fax control PCB.	Replace the fax control PCB and check for correct operation.
C082	**Fax control PCB CG ROM checksum error** • A checksum error occurred with the CG ROM data in the flash ROM on the fax control PCB.	Defective fax control PCB.	Replace the fax control PCB and check for correct operation.