Knowledge Data Base (KDB No.: KB0000008 / Status: Close)

****** PMN ******

Model:
Di620

Problem Machine:
Di620

Title:
Notes when Print Adaptor KIT is installed

Symptom:
Others / Others(Others)

Symptom Explanation:

Notice:
When Print Adaptor is installed to operate Di620 as MicroPress, the following work needed to be done.

1. In case of Unspeed-up respondent machine(before S/No.xx9220)
After "Print adaptor 06211/F KIT #4623-131(for the printer before speed-up)" is installed
please improve the following program in version.

1) after IC26IB:23G028-00(after P/No.1155-6607-49)
Note 1) It is reported with S/B No.1155-028C.
2) IC70B:10G055-00
Note 2) It is possible to obtain from SW/FW Download Service.
3) IC2A:50G019-00
Note 3) IC2A(2) which memories this version is newly established as market parts.

2. In case of speed-up respondent machine(after S/No.xx9221)
After " Print adaptor 06211/F KIT #4623-132(for the printer after speed-up)" is installed,
please improve the following program in version.

1) after IC70B:10H004-00(after P/No.:1155-0756-03)
Note 4) It is reported with S/B No.1155-040E.
2) IC2A:50H019-00
Note 5) The program of IC2A(3) on the print board A is changed.

(Change Execution S/No: xx14869~)

Temporary Measure:

CounterMeasure:

Cause:

Problem Rank:

C Check

Parts Modification Notice:

Ref.No.:

SW/FW Distribution:

Category:

PPC\Digital-B/W

Expand Machine:

Di620(Main Unit)
Di620PE(Main Unit)
Di621(Main Unit)

Cause Area:

Firmware

Original Report:

Information Date:

22.12.99

Edit Date:

22.12.99

Created by:

koji tokuyama/minolta