Knowledge Data Base (KDB No.: KB9900328 / Status: Close)

****** PMN ******

Model:
Di620

Problem Machine:
Di620

Title:
Noise is produced from the Duplex Unit.

Symptom:
Noise / Others(Noise)

Symptom Explanation:
Noise is produced from the Duplex Unit during making copies.

Temporary Measure:

CounterMeasure:
In order for Joints to engage properly, the shaft (1155-5770-02) has been extended for 2mm.
Effective S/N of the machines: XX10506 and onward
This part will be set as a field installable part later.

Please refer to the following Instructions when replacing.



Instructions.PDF

Cause:
The Joint of the Main Unit doesn't engage well with the Drive Joint of the Duplex Unit.

Problem Rank:
C Check

Parts Modification Notice:
Ref.No.:

SW/FW Distribution:

Category:
PPC\Digital-B/W

Expand Machine:
D5200iD(Main Unit)
D6200iD(Main Unit)
Di520(Main Unit)
Di521(Main Unit)
Di620(Main Unit)
Di621(Main Unit)
Di620PE(Main Unit)

Cause Area:
Paper Transport

Original Report:

Information Date:
22.11.99

Edit Date:

22.11.99

Created by:

nakao tsuji/minolta