


◆ Multi Bypass Misfeed Clearing Procedure

Symptom	Step	Check Item	Result	Action
	1	Is the paper fed out of the copier properly when it is taken up and fed in from the 1st or 2nd Drawer?	NO	Perform the troubleshooting procedure for "Copier Take-Up Misfeed" or "Transport/Separator Misfeed."
	2	Does the following message appear when a sheet of paper is placed on the Multi Bypass Table?  1136T058CA	NO	Remove the paper and perform step 3.
			YES	Perform step 4.
	3	Check Manual Feed Paper Empty Sensor PC51 as follows. (See p. T-5, 6.) 1) Port: P12-2		
		2) Select the function "Port." Is the data for P12-2 set to "H" (when no paper is loaded).  1136T059CA	NO	Check the actuator for operation.
		3) Move the actuator with a sheet of paper to block PC51. 4) Reselect "Port."  1136T060CA		
		5) Show the data for P12-2. Has the data changed from "H" to "L"?  1136T061AA	NO	Replace PC51.
			YES	Replace PWB-A.