Symptom	Step	Check Item	Result	Action
• Paper is stationary near the take-up port of the Duplex Unit.	1	Check Duplex Unit Paper Empty Sensor PC15 as follows. (See p. T-5, 6)		
		1) Move the actuator with a sheet or paper to block PC15.		
		2) Slide the Duplex unit back in.		
		3) Is the following message on the control panel ? Press the Start key to eject all the Copies at. 1136T150CA	YES	First replace PWB-G, then replace PF-202/PF-102 PWB-A, or EP2050 PWB-A, if necessary.
		4) Remove the sheet of paper to unblock PC15. 5) Select the function "Port." Is the data for P43-6 set to "H"? P41 ******** P42 11**1*01 ▶P43 ****LHHH ↓ 1136T091AA 6) Move the actuator with a sheet of paper to block PC15.	NO	• Check the actuator for operation. • Check PC15.
		7) Select "Port" again. Port Data ▶P0 1H11L*** P1 H1010111↓ 1136T092CA		
		8) Show the data for P43-6. Has it changed from "H" to "L"? P41 ******** P42 11**1*01 ▶P43 ****LLHH ↓ 1136T093AA	NO	Replace PC15.
			YES	First replace PWB-G, then replace PF-202/PF-102 PWB-A, or EP2050 PWB-A, if necessary.