* C0500, C0510

Step	Check Item	Result	Action
1	Does H1 light up when the Power Switch is turned ON?	YES	Check TH1/TH2 for installation or clean it.
		NO	Perform step 4.
2	Disconnect CN47 (4P). Is the resistance across CN47-2 and 3 on the Fusing Unit side infinity?	YES	Replace TH1.
		NO	Replace PWB-A.
3	Disconnect CN48 (4P). Is the resistance across CN48-2 and 3 on the Fusing Unit side infinity?	YES	Replace TH2.
		NO	Replace PWB-A.
4	Check the H1 ON/OFF signal from PWB-A when the Front Door is closed with S1 turned ON. (See p. T-3, 4.) 1) Port: P1-7 2) Select the function "Port."		
	3) Is the data for P1-7 set to "0"?  1136T108CA	NO	Replace PWB-A.
5	Disconnect CN4 (16P). Is there continuity across CN4-8 and 9 on the Fusing Unit side?	YES	Replace SSR.
		NO	Check H1 and TS1 for continuity.