* C0600, C0601

Step	Check Item	Result	Action
1	Is PJ6J securely plugged into PWB-J?	NO	Plug it in securely.
2	Is the voltage across PJ6J-6 on PWB-J and GND DC5V when the Power Switch is turned ON?	NO	Check the DC5V line.
3	Is C0600 being shown?	YES	Replace M2.
4	Is C0601 being shown?	YES	Replace PWB-J.

* C0650

Step	Check Item	Result	Action
1	Is PJ5J securely plugged into PWB-J and PJ43 into PC81?	NO	Plug them in securely.
2	Is the Light Blocking Plate installed properly?	NO	Reinstall it.
		YES	Replace PC81.

* C0660

Step	Check Item	Result	Action
1	Do you feel an overload when you move the Scanner manually with the Power Switch OFF?	YES	Correct or replace the Cables or part being overloaded.

* C06F0 to C06F7

Step	Check Item	Result	Action
1	Is PJ14AA securely plugged into PWB-A and PJ2J into PWB-J?	NO	Plug them in securely.
		YES	Replace PWB-A or PWB-J.