*C0d20

Step	Check Item	Result	Action
1	Does M32 turn when the Power Switch is turned ON or Duplex Unit slid into position?	NO	Replace M32, PWB-G, PF-202/PF-102/PF-2D PWB-A, or EP2050 PWB-A, in that order.
		YES	Check for possible overload.
2	Check PC8 as follows. (See p. T-5, 6.) 1) Block PC8. (The Trailing Gate Unit is at its home position.) 2) Port: P44-8 3) Select the function "Port."		
	4) Is the data for P44-8 set to "L"?  1136T141AA	NO	Replace PC8.
		YES	Replace PWB-G, PF-202/PF-102/PF-2D PWB-A, or EP2050 PWB-A, in that order.