*	Code	Description	Detection Timing
*	C0924	1st Drawer Paper Lift–Up Motor M13's failure to turn	• PC67 detects no pulses even after the lapse of 500 msec. after M13 has been energized. • PC67 detects no pulses for the period of 200 msec. while M13 is being energized.
	C0926	1st Drawer ejection failure	• The 1st Drawer is not ejected even after the lapse of 2 sec. after PC69 has been blocked (L).