Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : GP160 Series

No.: GP160-005
(FF-T01-E40-000038-01)

DATE: 10.08.99

Location : GP160 SERVICE INFORMATION

Subject : UPDATING THE SERVICE MANUAL

Reason : This bulletin communicates typographical mistakes found in the GP160 Series Service Manual (FY8-13G2-000). The corrections will be included in the next revision of the Service Manual.

Details :

Location: page 12-1, Table 12-201

Description: The part numbers of the No. 3 paper feed roller and the No.5 multi-feeder paper feed roller.

Correction:

No.	Name	Wrong	Correct
No. 3	Paper feed roller	RB2-1821-000	RB1-8865-000
No. 5	Multi-feeder paper feed roller	RB2-1820-000	RB2-1795-000