Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : **GP160** **GP160DF** **No.:** GP160-007
GP160F **GP160PF** (FF-T01-E40-000050-01)
DATE: 10.08.99

Destination :

F13-6744 GP160 EC	F13-6774 GP160 FRN	F13-6784 GP160 GER
F13-6794 GP160 HOL	F13-6724 GP160 ITA	F13-6754 GP160 UK
F13-6772 GP160DF FRN	F13-6782 GP160DF GER	F13-6792 GP160DF HOL
F13-6722 GP160DF ITA	F13-6741 GP160F EC	F13-6771-001 GP160F FRN
F13-6771 GP160F FRN	F13-6781-001 GP160F GER	F13-6781 GP160F GER
F13-6791 GP160F HOL	F13-6721 GP160F ITA	F13-6751-001 GP160F UK
F13-6751 GP160F UK	F13-6752 GP160F UK	F13-6775 GP160PF FRN
F13-6785 GP160PF GER	F13-6795 GP160PF HOL	F13-6725 GP160PF ITA
F13-6755 GP160PF UK		

Location : **G4/G3 Kit**

Subject : **Parts Addition**


Reason :

If the dead centre of the DIMM is pressed down forcefully,the pins of the IC chip could lift up.

Outline :

Seals will be attached at the two points described below,warning not to press down on the middle of the DIMM,but at both ends.

1. Accessory DIMM
2. Service parts FLASH ROM ASSEMBLY



Parts

Part Name		Part No.	Qty	IC
Old	FLASH ROM ASSEMBLY	FG2-9736-000	1	NY
New	FLASH ROM ASSEMBLY	FG2-9736-000	1	