Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : **GP160F**

No.: GP160-001
(FF-T01-E40-000028-01)

Date: 04.06.99

Destination :

F13-6751-001 GP160F UK	F13-6751 GP160F UK	F13-6752 GP160F UK
F13-6721 GP160F ITA	F13-6791 GP160F HOL	F13-6781-001 GP160F GER
F13-6781 GP160F GER	F13-6771-001 GP160F FRN	F13-6771 GP160F FRN

Location : **Feeder left cover unit**

Subject : **Parts deletion**

Reason : No problem with regard to strength.

Outline :

Of the four screws (XA9-1041) used to secure the LEFT COVER to the FEEDER LEFT COVER, the two that are not used for positioning will be deleted.

Refer to Parts Catalogue,p100.

Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : **GP160F**

No.: GP160-002
(FF-T01-E40-000029-01)

Date: 04.06.99

Destination :

F13-6771-001 GP160F FRN	F13-6771 GP160F FRN	F13-6781-001 GP160F GER
F13-6781 GP160F GER	F13-6791 GP160F HOL	F13-6721 GP160F ITA
F13-6751-001 GP160F UK	F13-6751 GP160F UK	F13-6752 GP160F UK

Location : **Main unit internal**


Subject : **Parts deletion**

Reason : May be removed without ill-effect.

Outline :

Parts Catalogue p102,No.14, FB4-5451 to be removed.

Refer to illustration below.



Caution

Parts catalogue p101,No.8,FB4-5451 is necessary,and will remain in use.

Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : **GP160F**

No.: GP160-003
(FF-T01-E40-000032-01)

Date: 04.06.99

Destination :

F13-6771 GP160F	FRN	F13-6781 GP160F	GER	F13-6791 GP160F	HOL
F13-6721 GP160F	ITA	F13-6751 GP160F	UK	F13-6752 GP160F	UK

Location : **PAPER PICK-UP ASSEMBLY**

Subject : **Shape modification**

Reason : To make the SENSOR HOLDER less prone to sticking.

Outline : SENSOR HOLDER shape to be modified.

Parts :

Part Name		Part No.	Qty	IC
Old	HOLDER,SENSOR	FB4-5665-000	1	NY
New	HOLDER,SENSOR	FB4-5665-020	1	
Old	PAPER PICK-UP ASSEMBLY	FG6-1278-000	1	NY
New	PAPER PICK-UP ASSEMBLY	FG6-1278-030	1	