
SERVICE BULLETIN


■ PROBLEM	● FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
□ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	○ OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 009
DATE : 980924
SUBJECT : IC26IB SOFTWARE PROGRAM CHANGE

PROBLEM: Due to a software bug, there is a possibility that the following problems may occur.
1) C-1468 (IC abnormal) mistakenly indicated.
2) If the Stop Key is pressed during the first paper feed in 2-in-1mode, the trouble code “C-11E7” may be mistakenly indicated.

SOLUTION: The software program of IC26IB (01) on P.W. BOARD-IB has been corrected.





Problem 1 solution — Problem 2 solution

EFFECTIVE MACHINE Se/No.: 000761 and onward — 001162 and onward

NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	11-32AA	1155-6607-36	1155-6607-48	11-32AB	IC	1	1	Y	001162	0000