
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 029
DATE : 990310
SUBJECT : BUSHING CHANGE

The material for bushing A (01) has been changed from plastic to metal. This prevents noise from occurring due to vibration while the copier is being driven.

The material for bushing B (02) has not been changed because bushing B (02) is not affected by vibration.



NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →	I	SE/NO.	AREA
01			1274-2611-01	08-45AA	BUSHING	1	Y	006110	0000
02	08-12AA	1200-3121-07	1200-3121-07	08-12AB	BUSHING	2 1	–	006110	0000