
SERVICE BULLETIN

■ PROBLEM	● FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
□ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	○ OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 040E
DATE : 990823
SUBJECT : C11F4 INDICATED ERRONEOUSLY

PROBLEM: There is a possibility that C11F4 may be indicated erroneously.
SOLUTION: The software program of IC70B on P. W. Board-B has been changed. Due to this, the memory program of the memory card IC (01, 02) has been changed.



IC70B Version: 10H001-00 ➡ 10G004-00

NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	46-35CB	1155-0756-01	1155-0756-03	46-35CC	JIG MEMORY CARD	1	1	Y	012095	2705
02	46-35EA	1155-0756-01	1155-0756-03	46-35EB	JIG MEMORY CARD	1	1	Y	012095	2704