
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 040Q
DATE : 990916
SUBJECT : SOFTWARE PROGRAM OF IC2A ON PWB-A CHANGE

In the Di520, the software program of IC2A (01) on P. W. Board-A has been changed and the following modifications have been implemented.

1. In the machine equipped with the FN-102 or FN-502, the productivity has been improved when the sort, group or staple mode is selected.
2. In the machine equipped with the FN-3, a paper jam in the FN-3, which occurs due to a software bug if the criss-cross mode operates when 2-sided copy mode is combined with sort or group mode, has been prevented.



NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →	I	SE/NO.	AREA
01	36-79CB	1155-6647-02	1155-6647-03	36-79CC	IC	1	1	Y 014889	2705