Canon **SERVICE BULLETIN** **COPIER**

Issued by Canon Europa N.V.

Model: Printer Board-P2

No.: GP-GEN-003
(97QAB-0039)
DATE: 19.12.97

LOCATION: Printer Board-P2
SUBJECT: Firmware Version Up (ver. 15.12)

1. Outline

Printer Board-P2 (PCL5e Printer Board for GP55-30) Ver.15.12 was released.

2. Details

As Printer Board-P2 ver.15.12 was released, the modification from ver.12.03 fixes the following problem:

- The data transferring via NIB-E2/E2e has some difficulty and the printing job fails.

3. Combinations of ROMs

GP55F	MMI	Ver.50.18	MDC	NCORE	Ver.84.02 and later
	IP	Ver.43.01		NIB-E2	Ver.31.04
	D-Con	Ver.22.01		NIB-E2e	Ver.2.25
				PCL5e	Ver.15.12
GP30F	ICORE	Ver.32.01 and later			
	IP	Ver.17.01 and later			
	D-Con	Ver.3.01			