Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : **ADF H1**

No.: DF-143
(FF-T01-E40-000048-01)

DATE: 10.08.99

Destination : F24-9612 ADF-H1 F24-9622 ADF-H1 F24-9632 ADF-H1

Location : **Document feed assembly**

Subject : **Shape modification**

Reason :

To further improve the meshing of ADF gears.

Outline :

HS5-1046

Dimensions changed in order to reduce the gap between the gears.

HB1-2016

Rib added to prevent ADF unit from lifting up.

The modified unit (FG6-1314-000) will be stocked as a service part.

Parts

Part Name		Part No.	Qty	IC
Old	MOUNT,DRIVE	HS5-1046-000	1	NY
New	MOUNT,DRIVE	HS5-1046-020	1	
Old	COVER,COPYBOARD	HB1-2016-000	1	NY
New	COVER,COPYBOARD	HB1-2016-030	1	