Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model : GP555

No.: GP605-011
(FF-T01-K1-000028-01)

DATE: 10.08.99

Location : INTRODUCING A NEW PRODUCT

Subject : INTRODUCING THE GP555

Reason : The GP555 will soon be marketed, and this bulletin communicates the differences from the GP605.

Details : < Differences in Specifications >
The copying speed is 55 cpm max. (A4/LTR).
The original orientation detection mechanism has been removed.

< Serial Numbers >

GP555	230V	F13-5682:	ANC00001 or later
		F13-5672:	BNC00001 or later
		F13-5692:	CNC00001 or later
		F13-5652:	DNC00001 or later
		F13-5622:	FNC00001 or later

Servicing : For information on servicing, see the GP605 Service Manual (FY8-13FD-000).
For information on parts, see the GP605 Parts Catalog (FY8-31DU-010).

Service Parts : Differences from the GP605

FIGURE & KEY No.	GP605 Part number	GP555 Part number	Q'ty	Description	Remarks
100-65	As single part	FG6-5390-000	1	Front Cover	
950	FG6-1911-000	FG6-5323-000	1	Image Processor PCB	
970	FG6-1946-000	——	0	Original Orientation Detection PCB	