■ 7020 OVERALL WIRING DIAGRAM



[HOW to see the diagram]

1. The signals shown reflect levels present under normal idling conditions with the main switch turned ON.
2. Wiring symbols in the figure are as follows.
   1) ⟶⟶ is Connector
   2) (RC) is ribbon cable
   3. Signal symbols in the figure are as follows .

[H] High active
[L] Low active
[*] Analog signal
[P] Pulse signal