1 SERVICE INSTRUCTION

1-1. PARTS WHICH MUST NOT BE TOUCHED

(1) Screws

Purpose of Application of Red Paint


Red paint is applied to the screws which cannot be readjusted, set, or reinstalled in the field. The basic rule is not to remove or loosen the screws to which red paint is applied. In addition, be advised that, if two or more screws are designated as those which must not be touched on a single part, only one representative screw may be marked with red paint.

(2) Variable Resistors on Boards


Do not turn the variable resistors on boards for which no adjusting instructions are given in "ADJUSTMENT."

(3) Other Screws

Original Glass Positioning Bracket (2 screws)



Lower Pre-Image Transfer Guide Plate (2 screws)



1-2. READING THE TEXT

The disassembly order is indicated by the corresponding number in the illustration.
For parts that require special attention and service jobs, they are given inside a separate frame.

