
Fig. 1
Removal of the CCD Assy



Parts to be Taken Apart in the Rear

