4-2. Tech. Rep. Mode Function Setting Procedure

<Procedure>

1. Press the Meter Counter key, then perform the following steps to enter the Tech. Rep. mode.

   Press the Stop key. ➡ Press "0." ➡ Press "0." ➡

   Press the Stop key. ➡ Press "0." ➡ Press "1."

2. From the Keypad, enter the number that corresponds to the service mode no. assigned and then press the Start key.
3. Perform the necessary steps for the function selected.

<Leaving the Tech. Rep. Mode>

- Press the Panel Reset key.