
(10) C0990: Main Tray Upward Motion Failure
C0991: Main Tray Downward Motion Failure
C0992: Main Tray Downward Motion Failure
C0993: Main Tray Upward Motion Failure
C0994: Elevator Motor's Failure to Turn

Relevant Electrical Parts	
Main Tray Lower Position Sensor PC2	Elevator Motor M26
Elevator Motor Pulse Sensor PC5	Cabinet Transport Board PWB-H
3rd Drawer Lift-Up Sensor PC19	PF-114 Master Board PWB-A
Lower Limit Position Sensor PC35	



1177C14TAB