
FUSING SECTION
Thermistor
TH1
CN14
Paper Exit Sensor
PC53
PJ12
CN22
Fusing Thermoswitch
TS1
CN5
Heater Lamp
H1
DEVELOPING SECTION
Upper Drive Motor
M1
PJ4
Toner Replenishing Motor
M8
CN20
Toner Bottle Home Position Sensor
PC112
PJ11
Drum Dehumidifying Heater
H2
CN12
CN17
CN18
ATDC Sensor
UN3
PJ16
CN39
Main Erase Lamp
LA2
PJ13
TRANSPORT SECTION
Synchronizing Roller Clutch
CL1
CN31
Transport Roller Clutch
CL2
CN30
Suction Fan Motor
M4
CN32
HV
High Voltage Unit
CN1HV
I.T./P.S. CH #1
P.C CH #2
Grid
Paper Leading Edge Sensor
PC54
PJ9
CN25
Transport Roller Sensor
PC51
PJ10
IR SECTION
PH SECTION
Polygon Motor
M6
PJ61
CN9
PJ1B
PJ3B
PWB-B LD Board
PJ2B
PWB-C SOS Sensor Board
PJ1C
PJ39A
PJ38A
PJ45A
Not Use
PJ44A
Not Use
PJ1A