MINOLTA

Service Bulletins
Parts Modification Notices
Knowledge Data Base

Di 620

SB/PMN-File	KDB-File	Title
1155001		P.W. BOARD-F CHANGE
1155002		CORRECTION OF SERVICE MANUAL
1155003		CORRECTION OF SERVICE MANUAL
1155003A		CORRECTION OF SERVICE MANUAL
1155004		SUPPLEMENTARY INFORMATION FOR PARTS MANUAL
1155005		HARNESS CHANGE
1155006		SUPPLEMENTARY INFORMATION FOR PM
1155006B		STANDARDIZATION OF PARTS
1155007		MANUAL FEED SECTION CHANGE
1155007B		P/NO. FOR PARTS OF Pi6000
1155007C		CB LABEL ADDITION
1155007E		PARTS FOR BLUE ANGEL MARK
1155007F		ROM FOR MESSAGE DISPLAY NEWLY MADE
1155008		SOFTWARE PROGRAM OF IC ON PWB-W CHANGE
1155009		IC26IB SOFTWARE PROGRAM CHANGE
1155009B		CORRECTION OF SERVICE MANUAL
1155010		EDGE COVER CHANGE
1155011		SOFTWARE PROGRAM OF IC70B ON PWB-B CHANGE
1155012		TAKE-UP MISFEED IN C-304L
1155013		P/NO. FOR PARTS OF HARD DISK KIT
1155014		CLEANING ROLLER KIT NEWLY MADE
1155014A		P/NO. FOR PARTS OF CONTROL PANEL
1155015		PM, SB, AND EXCLUSIVE PARTS FOR Di520
1155016		SHAPE OF THE PAWL CHANGE
1155017		SOFTWARE PROGRAM OF IC70B ON PWB-B CHANGE
1155018		SHAPE OF THE GEAR CHANGE
1155018C		STATUS MONITOR DISPLAY FAILURE
1155019		HOLDER CHANGE

SB/PMN-File	KDB-File	Title
1155020		CORRECTION OF SERVICE MANUAL
1155021		CORRECTION OF SERVICE MANUAL
1155022		CORRECTION OF SERVICE MANUAL
1155023		SOFTWARE PROGRAM FOR IC2A ON PWB-A CHANGE
1155024		PWB-HV CHANGE
1155025		CORRECTION OF SERVICE MANUAL
1155026		CORRECTION OF SERVICE MANUAL
1155027		CORRECTION FOR PARTS MANUAL
1155028		POLYESTER FILM ADDED
1155028A		CORRECTION OF SERVICE MANUAL
1155028C		SOFTWARE PROGRAM FOR IC21B ON PWB-B CHANGE
1155028E		COUNTERMEASURE FOR BLACK STREAKS WHEN EDH IS USED
1155029		BUSHING CHANGE
1155029A		HARD DISK ADDITION
1155030		NEW PM PART
1155030A		PROVISIONS FOR NEW BLUE ANGEL MARK
1155031		TONER BOTTLE LABEL CHANGE
1155031C		CORRECTION FOR INSTRUCTIONS
1155032		COVER CHANGE
1155033		BACKUP MEMORY RAM PROVIDED
1155033A		PRINTING SPEED INCREASED
1155034		REGULATING PLATE NEWLY MADE
1155035		CHANGE OF CABLE MOUNTING BRACKET
1155036		BRACKET FOR PWB-R ADDED
1155037		NOISE FROM THE CLEANING UNIT
1155037D		“DiALTA” LABEL ADDITION
1155037F		LABEL ADDITION
1155038		C0110 DISPLAY
1155039		P/NO. FOR THE HOLDER
1155040		HARNESS CHANGE
1155040C		ROM FOR MESSAGE DISPLAY NEWLY MADE
1155040E		C11F4 INDICATED ERRONEOUSLY
1155040H		SOFTWARE PROGRAM CHANGE FOR Pi6200
1155040L		SOFTWARE PROGRAM OF IC26IB ON PWB-IB CHANGE
1155040Q		SOFTWARE PROGRAM OF IC2A ON PWB-A CHANGE
1155041		PLATE SPRING ADDED

SB/PMN-File	KDB-File	Title
1155042		CORRECTION FOR PARTS MANUAL
1155043		LOSS OF IMAGE
1155044		DIMENSIONS OF SHAFT CHANGE
1155045		CORRECTION FOR PARTS MANUAL
1155046		PROGRAM OF IC2A CHANGE
1155048		IC26IB CHANGE
	KB9900282	ROM History of Firmware
	KB9900328	Noise is produced from the Duplex Unit.
	KB9900333	A failure occurs when the 2nd Drawer (Universal Tray) is empty.
	KB9900382	Matters that require attention when connecting the Pi6200 to the upgraded Di620/520
	KB0000005	PC Drum Paper Seperator Marks
	KB0000008	Notes when Print Adaptor KIT is installed
	KB0000054	Di620 doesn’t print the job until you press the start-key when a job without stapling is sent in case staples are empty.
	KB0000059	Error Message / Indicates "C"
	KB0000064	Void images at the trailing edge
	KB0000119	Malfunction of panel display in the version upgrade of MSC
	KB0000127	Black Streaks in the Feeding Direction when EDH-1 is used