
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	● CORRECTION
	○ SAFETY REGULATION	○ OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 003A
DATE : 980610
SUBJECT : CORRECTION OF SERVICE MANUAL

Please amend your Service Manual according to the instructions given below.

1. Page: M-63



2. Page: M-102

Paper Separation
The Paper Separator Corona showers the underside of the paper with both positive and negative charges so that the paper can be easily separated from the PC Drum. In addition, two Paper Separator Fingers physically peel the paper off the surface of the PC Drum. (For details, see PAPER SEPARATOR FINGERS.)

CORRECT: three