

SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 008
DATE : 980924
SUBJECT : SOFTWARE PROGRAM OF IC ON PWB-W CHANGE

In the software program of IC2W (01) and IC3W (02) on P.W. Board-W, the unused portion of the program concerning the communication with Pi6000 has been discontinued. This modification does not affect the function.





NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	36-63AA	1155-6618-02	1155-6618-03	36-63AB	IC	1	1	Y	000856	0000
02	36-62AA	1155-6619-02	1155-6619-03	36-62AB	IC	1	1	Y	000856	0000