

SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 010
DATE : 981001
SUBJECT : EDGE COVER CHANGE

To increase production efficiency, the size of the edge cover has been increased and the harness has been made easier to install. Due to this, the dimensions of the bracket (01) have been change at the cutout for the edge cover.





NOTE: If the new bracket (01) is installed in premodification machines, the new edge cover (9384-2010-41) must be installed with it.

NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	04-14AA	1155-2407-01	4115-2407-01	04-14AB	BRACKET	2	2	Y	002538	0000