

SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 031
DATE : 990408
SUBJECT : TONER BOTTLE LABEL CHANGE

To clarify the steps in changing the Toner Bottle, an illustration has been added to the Toner Bottle label (01). Due to this change, the length of the Toner Bottle label (01) has been extended.





NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	01-19AB	1161-7329-12	1155-7342-01	01-19AC	LABEL TONERBOTTLE	1	1	Y	008094	0000