
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	● CORRECTION
	○ SAFETY REGULATION	○ OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 031C
DATE : 990428
SUBJECT : CORRECTION FOR INSTRUCTIONS

A mistake occurred in the “UNPACKING/SETTING-UP INSTRUCTIONS” of the “PS ROM Board” for Pi6000. The corrected “UNPACKING/SETTING-UP INSTRUCTIONS” will be packed with the PS ROM Board by March, 1999.

PAGE 1



PAGE 2

