
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 037D
DATE : 990623
SUBJECT : "DiALTA" LABEL ADDITION

The DiALTA Label (01) has been affixed to the Front Cover at the location shown below. The Label for the U.S. and Canada (02) has been newly made available as a field installable part.



NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →	I	SE/NO.	AREA
01			1155-7340-01	01-25CA	LABEL DIALTA	1	Y	009221	2705
02			1155-7340-01	01-25BA	LABEL DIALTA	1	Y	- - - - - -	2704