
SERVICE BULLETIN

☐ PROBLEM	○ FUNCTION	○ SAFETY
	○ SERVICEABILITY	○ OTHERS
■ OTHERS	○ PERFORMANCE	○ CORRECTION
	○ SAFETY REGULATION	● OTHERS

MODEL NAME : Di620
MODEL CODE : 1155
NO. : 040
DATE : 990729
SUBJECT : HARNESS CHANGE

To protect the toner bottle home position sensor (PC4) from static electricity, a grounding wire has been added to the harness (01). The grounding wire is secured with the bracket and axle plate.



NO.	BEFORE MODI. F-IND	BEFORE MODI. PART NO.	AFTER MODI. PART NO.	AFTER MODI. F-IND	PART NAME	QTY →		I	SE/NO.	AREA
01	16-46AB	1155-6861-01	1155-6861-02	16-46AC	WIRE HARNESS ASSY	1	1	Y	012513	0000