Knowledge Data Base (KDB No.: KB9900282 / Status: Close)

Model:
Di620
Problem Machine:
Di620
Title:
ROM History of Firmware
Symptom:
Others / Others(Others)
Symptom Explanation:

Notice:
Please be informed that the modification on the Firmware List.


Firmware.xls

Temporary Measure:

CounterMeasure:

Cause:

Problem Rank:
C Check
Parts Modification Notice:
Ref.No.:

SW/FW Distribution:

Category:
PPC\Digital-B/W
Expand Machine:
D5200iD(Main Unit)
D6200iD(Main Unit)
Di520(Main Unit)
Di521(Main Unit)
Di620(Main Unit)
Di621(Main Unit)
Di620P(Main Unit)
Cause Area:
Firmware
Original Report:

Information Date:
29.09.99
Edit Date:
29.09.99
Created by:
koji tokuyama/minolta