1-4. PARTS WHICH MUST NOT BE TOUCHED

(1) Red Painted Screws

Purpose of Application of Red Paint

Red painted screws show that assembly or unit secured by which can only be adjusted or set at the factory and shall not be readjusted, set, or removed in the field.
Note that when two or more screws are used on the part in question, only one representative screw may be marked with red paint.


(2) Variable Resistors on Board

Do not turn the variable resistors (potentiometers) on boards to which no adjusting instrcutions are given in "ADJUSTMENT".


(3) Other Screws

Although not marked with red paint, the following screws must not be loosened or readjusted.


One screw on the Scanner Roller Height Adjusting Plate




Three screws on Scanner Rail



Two screws on the Lens Rail



Two screws on the Lower Pre-Image Transfer Guide Plate



Two screws on the Mirror Motor Unit

