
2-4. Optical Section

(1) Cleaning of the Original Glass




Wipe clean the Original Glass with a soft cloth.


NOTE

The surface of the Original Glass is coated with conductive material. Do not use a wax based detergent.
An alcohol-dampened cloth may be used if the Glass is seriously contaminated.

(2) Cleaning of the Scanner Shaft




1. Remove two screws and the Original Width Scale.
2. Remove the Original Glass.



3. Wipe clean the Scanner Shaft with a soft cloth.

(3) Cleaning of the Scanner Rail



Wipe clean the Scanner Rail with a soft cloth.