1136C07M
LA1
TF2
PU2
(YL) CN24
(YL) CN7
PU3
L
N
PU19 (C1)
PU4AB
DC5V
L LA1 ON
露光ランプPWM
Exposure Lamp
Control PWM
IC4A
RA23A
IC14A
DA14A
DA13A
RA3A
IC14A
EEセンサ-出力電圧
EE Sensor
Output Voltage
DC12V
DA5A
CA1A
RA2A
IC1A
RA4A
IC14A
DC12A
GND
EEセンサ-ゲインPWM(パルス幅変調)
EE Sensor gain PWM
(Pulse Width Modulation)
PU33 (C1)
CU22 (CT)
PU4AA (C1)
PW8-A
PW8-H
R5H
IC1H
C4H
R4H
R3H
C5H
R10H
R9H
C5H
R8H
D1H
D1H
R11H
R12H
R13H
C3H
C8H
IC1H
C6H
C1H
R1H
PD1H
R2H
C2H
R7H
C7H
R6H