

PWB-A
IC5A
BPA2
80
RA40A
IC27A
DA37A
IC4A
APA0
48
RA23A
IC14A
DA14A
CR3
APC3
68
APC2
67
APC0
64
CR5A
BPB0
86
PJ14AA
M2
PWB-J
(UP-4)
PJ6J
GND
IC3J
BOUT1
OUT1
OUT1
BOUT2
OUT2
OUT2
F
R
PWM
IC2J
F OUT
R OUT
PWM OUT
IC1J
DC5V
(C1)
PJ2J
CHA
TRON
BASE
SCEND
ENABLE
SCAN
SHOME
(CT)
PJ43
(C1)
PJ5J
PC81
RC1