CONTENTS

C0993: Main Tray Upward Motion Failure
C0994: Main Tray Elevator Motor M26's Failure to Turn T-94
2-17. C0998: Shifter Transfer Failure
C0999: Shifter Return Failure
C099A: Shifter Return Failure
C099b: Shifter Transfer Failure
C099C: Shift Motor M27's Failure to Turn T-97
2-18. C0996: 3rd Drawer Lock Release Failure
C0F79: Paper Empty Sensor Failure T-100
2-19. C0d00: Duplex Unit Front/Rear Edge Guide Plates Home Position Detection Failure
C0d20: Duplex Unit Trailing Gate Unit Home Position Detection Failure
C0d50: Duplex Unit Drive Motor M31's Failure to Turn
C0d51: Duplex Unit Drive Motor M31 Turning at Abnormal Timing T-105

3 Power is not Turned ON T-109