
3. Misfeed Clearing Procedures

3-1. Copier Take-Up Misfeed



Symbol	Name
PC54	Transport Roller Sensor
PC56	1st Drawer Paper Take-Up Sensor
PC57	2nd Drawer Paper Take-Up Sensor
SL2	1st Drawer Paper Take-Up Solenoid
SL3	2nd Drawer Paper Take-Up Solenoid
CL1	Paper Transport Clutch
PWB-A	Master Board

