Symptom	Step	Check Item	Result	Action
• Paper is stationary at the Vertical Transport Section.	1	Are the Vertical Transport Rollers deformed, worn, or dirty with paper dust?	YES	Clean or replace the Vertical Transport Rollers.
	2	Is the Paper Take-Up Guide Plate or Vertical Transport Guide Plate dirty or deformed?	YES	Correct, replace, or clean the Guide Plate.
	3	Check 1st Drawer Paper Take-Up Sensor PC56 as follows. (See p. T-7.)		
		1) Select the function "Paper Path Sensor" and check to see if the data for sensor code 1 is set to "1."  1136T046CA 2) Move the actuator with a sheet of paper to block PC56.	NO	• Check the actuator for operation. • Check PC56.
		3) Has the data for 1 changed from "1" to "0"?	NO	Replace PC56.
		 1136T047CA	YES	Replace PWB-A.