Symptom	Step	Check Item	Result	Action
• Paper is stationary at the Transport Rollers.	1	Are the Transport Rollers deformed, worn, or dirty with paper dust?	YES	Replace or clean the Transport Rollers.
	2	Check Transport Roller Sensor PC54 as follows. (See p. T-7.)		
		1) Select the function "Paper Path Sensor" and check to see if the data for sensor code 9 is set to "1." Paper Path Sensor Check. 123456789ABCDE 11111111111111  1136T051CA 2) Move the actuator with a sheet of paper to block PC54.	NO	• Check the actuator for operation. • Check PC54.
		3) Has the data for 9 changed from "1" to "0"?	NO	Replace PC54.
		Paper Path Sensor Check. 123456789ABCDE 11111111011111  1136T052CA	YES	Replace PWB-A.