

3-7. Duplex Unit Vertical Transport Misfeed



1136T001AA

Symbol	Name
PC12	Duplex Vertical Transport Sensor 2
PC13	Duplex Unit Turnover Path Sensor
PC14	Duplex Unit Paper Entry Senso
PC15	Duplex Unit Paper Empty Sensor
PC30	Duplex Unit Vertical Transport Sensor 1
SL31	Duplex Unit Gate Switching Solenoid
SL5	Exit/Duplex Solenoid
M31	Duplex Unit Drive Motor
PWB-A	EP2050 Master Board
PWB-A	PF-202/PF-102/PF-2D Master Board
PWB-G	Duplex Unit Master Board



1136C25TAA