Symptom	Step	Check Item	Result	Action
• Paper is stationary near the Vertical Transport Section of the Duplex Unit.	3	Check Duplex Vertical Transport Sensor 2 PC12 as follows. (See p. T-5, 6) 1) Port: P8-3 2) Select the function "Port."		
		3) Is the data for P8-3 set to "H"? ▶P8 HHHH*HLH P9 HLLHHHLL P10 ********↓ 1136T079AA	NO	• Check the actuator for operation. • Check PC12.
		4) Move the actuator with a sheet of paper to block PC12. 5) Select "Port" again. Port Data ▶P0 1H11L*** P1 H1010111↓ 1136T080CA		
		6) Show the data for P8-3. Has it been changed from "H" to "L"? ▶P8 HHLH*HLH P9 HLLHHHLL P10 ********↓ 1136T081AA	NO	Replace PC12.
			YES	Replace EP2050 PWB-A.