	Code	Description	Detection Timing
Sensors	C0F02	Original Size Detecting Board UN2 malfunction	When S1 is turned ON: 1) The Busy signal remains HIGH or LOW for approx. 5,000 msec. or more. 2) Undefined data is input to master CPU.  1136T60TCA