

2. Troubleshooting Procedures

2-1. C0000: Main Drive Motor M1's Failure to Turn
C0010: Main Drive Motor M1 turning at abnormal timing

Symbol	Name
M1	Main Drive Motor
PWB-A	Master Board



1136T012AA



1136C07TAA