

2-2. C0040: Suction Fan Motor M4's Failure to Turn
C004A: Original Glass Cooling Fan Motor M5's Failure to Turn
C004b: Original Glass Cooling Fan Motor M5 Turning at Abnormal Timing



Symbol	Name
M4	Suction Fan Motor
M5	Original Glass Cooling Fan Motor
PWB-A	Master Board

1136T013AA



1136C09TAA